

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,733,649 B2
DATED : May 11, 2004
INVENTOR(S) : Martin Bleck et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 11,

Line 19, "filly" should be -- fully --;

Column 13,

Line 2, "a" should be -- as --;

Column 15,

Line 60, "stints" should be -- struts --;

Column 17,

Line 43, "fling" should be -- fixing --;

Line 49, delete "so" between "contacting" and "a";

Column 22,


Line 51, "axle" should be -- axis --;

Column 24,

Line 39, "en" should be -- an --;

Signed and Sealed this

Twenty-third Day of November, 2004



JON W. DUDAS

Director of the United States Patent and Trademark Office